Kimley-Horn and Associates, Inc.
Project Description for Signalized Intersection Priority: 5

Town of Addison
ADA Self-Evaluation and Transition Plan
063543021 Client: Program: KHA No.: Date: 1/2/18 Prepared By: CMP Checked By: EPE

Corridor : Project Name: Town: Addison Rd Intersection of Addison Rd and Westgrove Dr Addison GPS ID: 2

Item No.	Item Description	Quantity	Unit	Un	it Price	Item Cost
TxDOT 110-6001	EXCAVATION (ROADWAY)	0	CY	\$	10.00 \$	-
	CONC CURB (TY II)	0	LF	\$	15.00 \$	-
TxDOT 531-6001	CONC SIDEWALKS (4")	39	SY	\$	45.00 \$	1,755.00
TxDOT 531	CURB RAMPS	8	EA	\$	1,500.00 \$	12,000.00
	RETROFIT DET WARN SURF (CAST IN PLACE)	0	SF	\$	50.00 \$	-
TxDOT 104-6015	REMOVING CONC (SIDEWALKS)	60	SY	\$	9.00 \$	540.00
TxDOT 687-6002	PEDESTRIAN PUSH BUTTON POLE	0	EA	\$	1,400.00 \$	-
TxDOT 677	ELIM EXT PAVE MRK & MRKS	0	LF	\$	2.80 \$	-
TxDOT 666/678	REFL PAV MRK PREP, TY I & TY II (W) 24"(SLD)	522	LF	\$	8.50 \$	4,437.00
TxDOT 688-6001	PED DETECT PUSH BUTTON (APS)	8	EA	\$	1,300.00 \$	10,400.00
TxDOT 690-6030	REMOVAL OF PEDESTRIAN PUSH BUTTONS	8	EA	\$	125.00 \$	1,000.00
	RELOCATE PEDESTRIAN PUSH BUTTONS	0	EA	\$	300.00 \$	-
TxDOT 682-6018	PED SIG SEC (LED) (COUNTDOWN)	0	EA	\$	500.00 \$	-
	PEDESTRIAN PUSH BUTTON SIGN	0	EA	\$	150.00 \$	-
	REMOVE PEDESTRIAN PUSH BUTTON SIGN	0	EA	\$	50.00 \$	-
	REPAVE ROADWAY	4	LS	\$	5,000.00 \$	20,000.00
	FIX PONDING	1	LS	\$	2,000.00 \$	2,000.00
	FIX CURB RAMP TRANSITION	3	LS	\$	2,000.00 \$	6,000.00
	MEDIAN NOSE MODIFICATION	0	LS	\$	5,000.00 \$	-
	REMOVE TEMPORARY OBSTRUCTION	0	LS	\$	500.00 \$	-
	FIX CURB RAMP COUNTER SLOPE	0	LS	\$	2,000.00 \$	-
Basis for Cost Proje					Subtotal: \$	58,132.00
•	✓ No Design Completed			Engineering: (% +/	-) 20% \$	11,934.00
	□ Preliminary Design			Contingency: (% +/	-) 20% \$	11,934.00
	☐ Final Design				roject Cost: \$	82,000.00

# Project Location







## Field Observations

Intersection Issues		Cros	swalk	Possible Solutions		
Intersection issues	N	E	S	W	Possible Solutions	
Path of travel pavement condition	Dangerous	Dangerous	Dangerous	Dangerous		
Path of travel running slope is greater than 5%	X				Repave roadway and install crosswalk pavement markings	
Path of travel cross slope is greater than 5%		Χ				
Crosswalk width is less than 6'	N/A	N/A	N/A	N/A	Install crosswalk pavement markings	
Crosswalk striping condition	None	None	None	None	Ilistali crosswak pavement markings	

Curb Ramp Issues					ID ('z' or 'i' in ramp label indicates no existing ramp)	Possible Solutions
Out Namp issues	1A	2z	3A	4A		
Curb ramp does not exist and is needed		Χ				Install curb ramp; if median improvement, see shapefile
Curb ramp does not land in crosswalk						
No 4' x 4' clear space at base of curb ramp						
Curbed side is not 90° or has traversable adjacent surface						
Flare cross slope is greater than 10%	Х		Χ			
Curb ramp running slope is greater than 8.3%	Х			Х		
Blended transition running slope is greater than 5%						
Cut-thru ramp running slope is greater than 5%						Remove and replace curb ramp
Curb ramp cross slope is greater than 2%	Х					ivellione and replace only fallip
Cut-thru ramp cross slope is greater than 5%						
Curb ramp width is less than 48"	Х					
Cut-thru ramp width is less than 60"						
Permanent obstruction (>0.25") in curb ramp/landing/flares	Х					
Temporary obstruction (>0.25") in curb ramp/landing/flares						
No textured surface at base of curb ramp	Х		Χ	Х		For intersection, commercial driveway, and park ramps,
No color contrast at base of curb ramp	Х		Х	Х		install color truncated domes
Landing area does not exist and is needed				Χ		Install landing area
Landing area is less than 5' x 5' or slopes greater than 2%	Х		Χ			Remove and replace landing area
Missing or no pedestrian push buttons						
Pedestrian push button is offset more than 5' from the nearest						
crosswalk edge						
Pedestrian push button offset more than 10' from curb face						
Pedestrian push button is not parallel to crosswalk						
Pedestrian push button height is greater than 48"	<u> </u>					
Pedestrian push button diameter is not 2"	Χ	Χ	Χ	Χ		Remove PBs and replace with APS push buttons
Pedestrian push button sign does not exist						
Pedestrian push button sign is not MUTCD approved						
Clear floor space does not exist and is needed		Х	Χ			Install clear floor space
Clear floor space for pedestrian push button is less than 30" x 48" or	Х			Х		Remove and replace clear floor space
has a slope greater than 2%	^			^		Tromovo and ropidoo dodi noor space
Missing or no pedestrian signal heads	ļ					
Curb ramp transition onto roadway is greater than 0.25"	Χ		Χ	Χ		Fix curb ramp transition
Counter slope of the gutter or street at the foot of the curb ramp is						
greater than 5%	<u> </u>			ļ		
Ponding occurs at base of curb ramp	Χ					Fix ponding





Corner 2 No Ramp (2z)



Curb Ramp Recommendation Details: Types 1-11 (Standard Corner Ramp) Type 20 (Median Ramps with Shared Landing) Type 21 (Median Cut-thru Ramp) Type 22 (Channelizing Island Cut-thru Ramp) EA EA EA

### Opinion of Probable Construction Cost Disclaimer:

The Engineer has no control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable costs provided herein are based on the information known to Engineer at this time and represent only the Engineer's judgment as a design professional familiar with the construction industry. The Engineer cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable costs.

Project Location Map Sources:
Esri, DeLorme, NAVTEQ, USGS, Intermap, iPC, NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), TomTom, 2013, DigitalGlobe, GeoEye, i-cubed, USDA, AEX, Getmapping, Aerogrip, IGN, IGP, swisstopo, and the GIS User Community