Kimley-Horn and Associates, Inc. Project Description for Unsignalized Intersection Priority: 2


Client: Town of Addison Date: 1/2/18 Program: ADA Self-Evaluation and Transition Plan Prepared By: CMP KHA No.: 063543021 Checked By: EPE

Keller Springs Rd Intersection of Keller Springs Rd and Mary Kay Way GPS ID: 110 Corridor : Project Name: Town: Addison


Item No.	Item Description	Quantity	Un	ıit	Unit Price	Item Cost
TxDOT 110-6001	EXCAVATION (ROADWAY)	0	C)	Ý \$	10.00	\$ _
TxDOT 529-6002	CONC CURB (TY II)	0	LF	- \$	15.00	\$ -
TxDOT 531-6001	CONC SIDEWALKS (4")	7	S	Y \$	45.00	\$ 315.00
TxDOT 531	CURB RAMPS	6	E/	۹ \$	1,500.00	\$ 9,000.00
TxDOT 5003-6002	RETROFIT DET WARN SURF (CAST IN PLACE)	0	SF	- \$	50.00	\$ -
TxDOT 104-6015	REMOVING CONC (SIDEWALKS)	25	S	′ \$	9.00	\$ 225.00
	ELIM EXT PAVE MRK & MRKS	0	LF	- \$	2.80	\$ -
TxDOT 666/678	REFL PAV MRK PREP, TY I & TY II (W) 24"(SLD)	412	LF	- \$	8.50	\$ 3,502.00
	REPAVE ROADWAY	2	LS	3 \$	5,000.00	\$ 10,000.00
	FIX PONDING	0	LS	3 \$	2,000.00	\$ -
	FIX CURB RAMP TRANSITION	2	LS	3 \$	2,000.00	\$ 4,000.00
	MEDIAN NOSE MODIFICATION	0	LS	3 \$	5,000.00	\$ -
	REMOVE TEMPORARY OBSTRUCTION	0	LS	3 \$	500.00	\$ -
	FIX CURB RAMP COUNTER SLOPE	0	LS	3 \$	2,000.00	\$ -
Basis for Cost Projection					Subtotal:	\$ 27,042.00
	✓ No Design Completed			Engineering:		5,479.00
	□ Preliminary Design			Contingency		5,479.00
☐ Final Design					mated Project Cost:	\$ 38,000.00

☐ Final Design

Project Location







Field Observations

Intersection Issues		Cros	swalk		Possible Solutions	
		N E S		W	Possible Solutions	
Path of travel pavement condition	Poor	Good	N/A	Dangerous	Repave roadway and install crosswalk pavement markings	
Path of travel running slope is greater than 5%			N/A	X	rrepave roadway and install crosswalk pavement markings	
Path of travel cross slope is greater than 2% for stop control		N/A	N/A	N/A		
approaches		14/71	1471	14//		
Dath of travel areas clans is greater than 5% for free flow energoshes	N/A		N/A			
Path of travel cross slope is greater than 5% for free-flow approaches Crosswalk width is less than 6'	N/A	N/A	N/A	N/A		
Crosswalk striping condition	None	None	N/A	None	Install crosswalk pavement markings	
Crosswark striping condition	None	None	IN/A	None	·	

Curb Ramp ID ('z' or 'i' in ramp label indicates no							
Curb Ramp Issues				existing ram	mp) Possible Solutions		
	1A	2A	3 <i>z</i>	4z			
Curb ramp does not exist and is needed			Χ	Х	Install curb ramp; if median improvement, see shapefile		
Curb ramp does not land in crosswalk	<u> </u>		İ	<u> </u>			
No 4' x 4' clear space at base of curb ramp	<u> </u>	Х	İ	<u>i</u> j	Remove and replace crosswalk pavement markings		
Curbed side is not 90° or has traversable adjacent surface]				
Flare cross slope is greater than 10%			İ				
Curb ramp running slope is greater than 8.3%	l		<u> </u>				
Blended transition running slope is greater than 5%			ļ				
Cut-thru ramp running slope is greater than 5%					Remove and replace curb ramp		
Curb ramp cross slope is greater than 2%	X		<u> </u>	<u> </u>	Tremove and replace out ramp		
Cut-thru ramp cross slope is greater than 2%	<u> </u>		İ	<u> </u>			
Curb ramp width is less than 48"				<u> </u>			
Cut-thru ramp width is less than 60"	<u> </u>		<u> </u>	<u> </u>			
Permanent obstruction (>0.25") in curb ramp/landing/flares	Χ		<u> </u>	<u> </u>			
Temporary obstruction (>0.25") in curb ramp/landing/flares	<u> </u>		<u> </u>	<u> </u>			
No textured surface at base of curb ramp	X	Х	<u> </u>	<u> </u>	For intersection, commercial driveway, and park ramps, install		
No color contrast at base of curb ramp	X	Х	<u> </u>	.j	color truncated domes		
Landing area does not exist and is needed	<u> </u>	Χ	ļ	<u> </u>	Install landing area		
Landing area is less than 5' x 5' or slopes greater than 2%	X		<u> </u>	.l	Remove and replace landing area		
Curb ramp transition onto roadway is greater than 0.25"	X	Χ	<u> </u>	<u> </u>	Fix curb ramp transition		
Counter slope of the gutter or street at the foot of the curb ramp is			İ				
greater than 5%	<u> </u>		<u> </u>	<u> </u>			
Ponding occurs at base of curb ramp	i						

Photographs



Ramp 1A





Corner 3 No Ramp (3z)



Corner 4 No Ramp (4z)

Opinion of Probable Construction Cost Disclaimer:

The Engineer has no control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable costs provided herein are based on the information known to Engineer at this time and represent only the Engineer's judgment as a design professional familiar with the construction industry. The Engineer cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable costs.

Project Location Map Sources:

Esri, DeLorme, NAVTEQ, USGS, Intermap, iPC, NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), TomTom, 2013, DigitalGlobe, GeoEye, i-cubed, USDA, AEX, Getmapping, Aerogrip, IGN, IGP, swisstopo, and the GIS User Community