
Kimley-Horn and Associates, Inc. Project Description for Unsignalized Intersection Priority: 5

Client: Town of Addison Date: 1/2/18 Program: ADA Self-Evaluation and Transition Plan Prepared By: CMP KHA No.: 063543021 Checked By: EPE


Corridor : Project Name: Town: GPS ID: 157 Addison Rd Intersection of Addison Rd and driveway (Lat. 32.9570; Long. -96.8298) Addison

TxDOT 110-6001 EXCAVATION (ROADWAY) 0 CY \$ 10.00 \$ 10.00 \$ 15.00	Item Cost
TxDOT 531-6001 CONC SIDEWALKS (4*) 0 SY \$ 45.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 5   TxDOT 5003-6002 RETROFIT DET WARN SURF (CAST IN PLACE) 0 SF \$ 50.00 \$ 5 \$ 50.00 \$ 5 \$ 50.00 \$ 9.00 \$ 5 \$ 50.00 \$ 9.00<	-
TxDOT 531 CURB RAMPS 2 EA \$ 1,500.00 \$   TxDOT 5003-6002 RETROFIT DET WARN SURF (CAST IN PLACE) 0 SF \$ 50.00 \$   TxDOT 104-6015 REMOVING CONC (SIDEWALKS) 18 SY \$ 9.00 \$   TxDOT 6677 ELIM EXT PAVE MRK & MRKS 0 LF \$ 2.80 \$   TxDOT 666/678 REFL PAV MRK PREP, TY I & TY II (W) 24"(SLD) 0 LF \$ 8.50 \$    REPAVE ROADWAY 0 LS \$ 5,000.00 \$    FIX PONDING 0 LS \$ 2,000.00 \$	-
TxDOT 5003-6002 RETROFIT DET WARN SURF (CAST IN PLACE) 0 SF \$ 50.00 \$   TxDOT 104-6015 REMOVING CONC (SIDEWALKS) 18 SY \$ 9.00 \$   TxDOT 677 ELIM EXT PAVE MRK & MRKS 0 LF \$ 2.80 \$   TxDOT 666/678 REPL PAV MRK PREP, TY I & TY II (W) 24"(SLD) 0 LF \$ 5.00.00 \$    REPAVE ROADWAY 0 LS \$ 5.000.00 \$    FIX PONDING 0 LS \$ 2.000.00 \$	-
TxDOT 104-6015 REMOVING CONC (SIDEWALKS) 18 SY \$ 9.00 \$   TxDOT 677 ELIM EXT PAVE MRK & MRKS 0 LF \$ 2.80 \$   TxDOT 666/678 REPL PAV MRK PREP, TY I & TY II (W) 24"(SLD) 0 LF \$ 5.00 \$    REPAVE ROADWAY 0 LS \$ 5.00 \$    FIX PONDING 0 LS \$ 2.000 \$	3,000.00
TxDOT 677 ELIM EXT PAVE MRK & MRKS 0 LF \$ 2.80 \$   TxDOT 666/678 REFL PAV MRK PREP, TY I & TY II (W) 24"(SLD) 0 LF \$ 8.50 \$    REPAVE ROADWAY 0 LS \$ 5,000.00 \$    FIX PONDING 0 LS \$ 2,000.00 \$	-
TxDOT 666/678 REFL PAV MRK PREP, TY I & TY II (W) 24"(SLD) 0 LF \$ 8.50 \$    REPAVE ROADWAY 0 LS \$ 5,000.00 \$    FIX PONDING 0 LS \$ 2,000.00 \$	162.00
REPAVE ROADWAY 0 LS \$ 5,000.00 \$ FIX PONDING 0 LS \$ 2,000.00 \$	-
FIX PONDING 0 LS \$ 2,000.00 \$	-
	-
	-
FIX CURB RAMP TRANSITION 1 LS \$ 2,000.00 \$	2,000.00
MEDIAN NOSE MODIFICATION 0 LS \$ 5,000.00 \$	-
REMOVE TEMPORARY OBSTRUCTION   0 LS   \$ 500.00   \$	-
FIX CURB RAMP COUNTER SLOPE 0 LS \$ 2,000.00 \$	-
Basis for Cost Projection Subtotal: \$	5,162.00
☑ No Design Completed Engineering: (% +/-) 20% \$	1,419.00
☐ Preliminary Design Contingency: (% +/-) 20% \$	1,419.00
☐ Final Design Estimated Project Cost: \$	8,000.00

## Project Location







## Field Observations

Intersection Issues	Crosswalk				Possible Solutions		
	N	E	S	W	Fossible Solutions		
Path of travel pavement condition							
Path of travel running slope is greater than 5%							
Path of travel cross slope is greater than 2% for stop control	All driveway path of travel issues and possible solutions provided in driveway shapefile (TRPEDDRV)						
approaches							
	, u.	pai		o ana poconono	columnia provided in dividual chapolile (1111 252111)		
Path of travel cross slope is greater than 5% for free-flow approaches							
Crosswalk width is less than 6'							
Crosswalk striping condition							

	Curb	Ramp	ID ('z' or 'i' in ramp label indicates no	
Curb Ramp Issues			existing ramp)	Possible Solutions
	1A	4A		
Curb ramp does not exist and is needed				
Curb ramp does not land in crosswalk	İ			
No 4' x 4' clear space at base of curb ramp	İ			
Curbed side is not 90° or has traversable adjacent surface				
Flare cross slope is greater than 10%				
Curb ramp running slope is greater than 8.3%	]			
Blended transition running slope is greater than 5%	İ			
Cut-thru ramp running slope is greater than 5%				Remove and replace curb ramp
Curb ramp cross slope is greater than 2%	Χ	Х		Tremove and replace outs ramp
Cut-thru ramp cross slope is greater than 2%	<u> </u>			
Curb ramp width is less than 48"	<u> </u>			
Cut-thru ramp width is less than 60"	<u> </u>			
Permanent obstruction (>0.25") in curb ramp/landing/flares	ļ			
Temporary obstruction (>0.25") in curb ramp/landing/flares	ļ			
No textured surface at base of curb ramp	ļ			
No color contrast at base of curb ramp	ļ			
Landing area does not exist and is needed	ļ <u>.</u>			Daniel de la contraction de la
Landing area is less than 5' x 5' or slopes greater than 2%	X			Remove and replace landing area
Curb ramp transition onto roadway is greater than 0.25"	X			Fix curb ramp transition
Counter slope of the gutter or street at the foot of the curb ramp is				
greater than 5%	ļ			
Ponding occurs at base of curb ramp	į į			

**Photographs** 







Ramp 4A

## Opinion of Probable Construction Cost Disclaimer:

The Engineer has no control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable costs provided herein are based on the information known to Engineer at this time and represent only the Engineer's judgment as a design professional familiar with the construction industry. The Engineer cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable costs.

## Project Location Map Sources:

Esri, DeLorme, NAVTEQ, USGS, Intermap, iPC, NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), TomTom, 2013, DigitalGlobe, GeoEye, i-cubed, USDA, AEX, Getmapping, Aerogrip, IGN, IGP, swisstopo, and the GIS User Community