EMBREY BUILDERS, LLC. 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209

Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Trent Perkins Parkin Perkins Olsen 9330 LBJ Freeway, Suite 1055 Dallas, TX 75243 Ph: (214)221-2220 Fax: (214)221-2252

RFI #: 87 Date: 3/27/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

cc: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: Brick Ledge at 10" Drop in Slab


Drawing: A3.1B and S2.12 Cost Impact: None


Spec Section: Schedule Impact: None


Date Required: 4/3/2012 Request: On the left hand side of the attached drawings, please provide a blow up of the area that the brick ledge is located and the two slabs are at different elevations. How does the 3/4" gap on the back side of each wall tie into the brick ledges at different levels? See Detail 7/S3.04 that shows the air gaps behind the walls. Requested by: David Miller Embrey Builders LLC

Response: I've talked with Trent Perkins about detail 7/ S3.04 and it will be revised to match my comments on the next pages of this PDF. Ryan Faulds Answered by BGO architects April 04, 2012

Page 1 of 1







EMBREY BUILDERS, LLC.

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Erik Earnshaw Beeler Guest Owens Architects 4245 N. Central Expressway Suite 300 Dallas, TX 75205

RFI #: 88 Date: 3/27/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

cc: Trent Perkins (Parkin Perkins Olsen)

Ph: 214/520-8878 Fax: 214/520-8879

Subject: Exposed Concrete/Drop in Slab Elevations

Drawing: A3.1B & S2.12 Cost Impact: None


Spec Section: Schedule Impact: None

Date Required: 4/3/2012 See the attached drawings. The walls shaded in purple show where the slab drops. There will be exposed concrete in certain areas. We would like to see the following:

1. Typical cuts in the areas indicated showing how to finish the bottom of the wall.

2. A blow up detail showing the area on the right side in the corner where the two slabs are at a different elevation. Request:

Requested by: David Miller Embrey Builders LLC



Page 1 of 1

Embrey Builders, LLC 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Erik Earnshaw Beeler Guest Owens Architects 4245 N. Central Expressway Suite 300 Dallas, TX 75205

Ph: 214/520-8878 Fax: 214/520-8879

RFI#: 169 Date: 7/9/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

Request:

Subject: Ceiling Heights

Drawing: A3.1B & A3.1D

Spec Section:

1. Please confirm that the ceiling height of the A1 unit (#1118) is 10'-11 1/8". Sheet A3.1A shows it to be that measurement, but

Schedule Impact: None Cost Impact: None

A3.1B shows it to be something else.

2. Please confirm ceiling heights of the A4 units on A3.1D. Shouldn't they be 10'-1 1/8"?

3. Please confirm the ceiling height of the A2 units on A3.1D. One has 10'-1 1/8" and I think it should be 10'-7 1/8".

Requested by: David Miller

Embrey Builders LLC

1. drawing A3.1A is correct, and A3.1B is incorrect.

2&3 on sheet A3.1D, starting with the ceiling height of unit A3 on the far right facing the pool courtyard= 10' - 1 1/8". going clockwise around the courtyard from there we get

A3= 10'- 1 1/8" (no change, but when you see *** that means change)
A2= 10'- 7 1/8" due to drop in foundation

A4= 10'- 1 1/8*** because we step back up in the foundation A4= 10'- 1 1/8" ***

Answered by: Erik Earnshaw

Answered date: September 05, 2012

Page 1 of 1

Date Required: 7/13/2012

