EMBREY BUILDERS, LLC. 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI RFI#: 109 To: Erik Earnshaw Date: 4/16/2012 Beeler Guest Owens Architects Job: EB-02 Keller Springs Lofts 4245 N. Central Expressway Phone: 877-777-5115 Suite 300 Dallas, TX 75205 Ph: 214/520-8878 Fax: 214/520-8879 CC: Trent Perkins (Parkin Perkins Olsen), Enviro Design Landscape Subject: Elevation Discrepencies Spec Section: Drawing: A3.1C, 2C & S2.13 Schedule Impact: None Cost Impact: None Date Required: 4/20/2012 Architecturals and Structural plans show FF at 640.6'. Landscape shows 641.6. Please confirm the correct elevation is 640.6'. Architecturals show a spot elevation outside the building at 640.5'. Landscape shows a spot elevation of 640.1' at the bottom of the ramp and 640' in the street just outside. Please confirm the correct spot elevations. Requested by: David Miller Embrey Builders LLC \* THE CORRECT FINISH FLOOR GUNATION IS 640.60. WE WILL UPDATE OUR DRAWING. SPOT GRADES ADJACENT TO EXTERIOR OF UNIT ARE CORRECT AS SHOWN. \* THE SPOT ELEVATION AT THE BOTTOM OF RAMP SHOULD ELE 640.10, AND THE LANDING AREA AT THE PERSON OF RAMP CALL NOT EXCEDE 29/3 CROSS SLATE. 04-16-12-ENVIRO DESIGN

~~~~ \*YERIFY- 6" RISE FROM STREET PAVEMENT GRADE ON RAMP GENERAL NOTES:

1. MAXIMUM 2% CROSS SLOPE
ON WALKS.
2. MAXIMUM 5% (1:20) RUNNING
SLOPE ON WALKS EXCEPT
AT A CURB RAMP.
3. SPOT GRADES SHOWN AT
TOP OF CURB RAMP TO
BE VERIFIED WITH FIELD
CONDITIONS. CONCRETE PAVER ON RECESSED
CONCRETE SLAB, HOLLAND STONE
(80011) IN RUNER BOND PATTERN.
COLOR TO BE OLD TOWN BLEND.—
AVAILABLE FROM
PAVESTONE COMPANY,
81T-481-5802 (JOEY GUEDEA) TRANSFORMER REVISION
AND ADDED SIDEWALK TO
STREET √3 |17 OCT 20|| FLATWORK AND GRADE REVISIONS DUE TO BUILDING REVISIONS ∕5\02 FEB 2012 GRADE REVISIONS DUE TO CIVIL COORDINATION 6 26 APR 2012 8 13 DEC 2012 SPOT GRADES FOR WALK STAKING

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

To: Jordan & Skala Engineers, Inc. 14240 Midway Road, Suite 350 Dallas, TX 75244 Ph: 469/385-1616 Fax: 469/385-1615

RFI#: 45 Date: 1/27/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

Page 1 of 1

**EMBREY BUILDERS, LLC.** 

1020 N. E. Loop 410, Suite 700

cc: Enviro Design Landscape

Subject: Relocation of fountain equipment vault

Enviro Design

Company

Cost Impact: None

Spec Section: Schedule Impact: None

Date Required: 2/3/2012 Our pool contractor has proposed a change in location and elevation for the fountain equipment vault. Attachment # 1 shows RFI for the location of the CF panel in the courtyard. Attachment #2 shows proposed relocation of the vault and shows location of CF panel. Attachment #3 is a background e-mail. Attachment #4 is the detail sketch from the pool contractor.

Requested by: Bryan Pickler Embrey Partners, Ltd. The relocation of the vault is acceptable to us so long as it is positioned so that the River Birch can stay in place. The Dwarf Yaupons can terminate where they meet the new vault location and groundcover and be filled in around the front. We will revised our drawings and submit revised sheets which will incorporate RFI #35 as well. Thank you Brian Arthur Answered by January 27, 2012

San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656 RFI To: Jordan & Skala Engineers, Inc. RFI#: 45 14240 Midway Road, Suite 350 Date: 1/27/2012 Dallas, TX 75244 Job: EB-02 Keller Springs Lofts Ph: 469/385-1616 Fax: 469/385-1615 Phone: 877-777-5115 cc: Enviro Design Landscape Subject: Relocation of fountain equipment vault Spec Section: Schedule Impact: None Cost Impact: None Date Required: 2/3/2012 Our pool contractor has proposed a change in location and elevation for the fountain equipment vault. Attachment # 1 shows RFI for the location of the CF panel in the courtyard. Attachment #2 shows proposed relocation of the vault and shows location of CF panel. Attachment #3 is a background e-mail. Attachment #4 is the detail sketch from the pool contractor. Requested by: Bryan Pickler Embrey Partners, Ltd. JSE Response Electrical: Panel 'CF' serves the fountain courtyard and the fountain equipment. - Mike Jennings, Jordan & Skala 2/6/2012 Plumbing: The email mentions connecting the vault to storm sewer. The civil engineer provided the courtyard drainage and if a connection is made, it would need to be coordinated with them. Heath Parnell, Jordan & Skala 2/6/12 Answered by

RFI RFI#: 35 To: Enviro Design Landscape 7424 Greenville Ave, Suite 200 Date: 1/19/2012 Job: EB-02 Keller Springs Lofts Dallas, TX 75231 Ph: 214/987-3010 Fax: 214/987-3015 Phone: 877-777-5115 cc: David Gallagher (Embrey Build (Embrey Construction LLC) Subject: Elevation conflict on sheet 2C Spec Section: Drawing: 2C Schedule Impact: None Cost Impact: None Date Required: 1/26/2012 Landscape sheet 2C needs to be coordinated and revised to reflect the revised paving elevations on revised civil sheet C4 (11/17/11). There are areas of conflict of up to 1' between drawings. Requested by: Bryan Pickler Embrey Partners, Ltd. Attached please find the following sheets with the revised grades as coordinated with the Civil and Architect: Construction sheets 2C, 3C, 7C; Partial breezeway plan prepared by BGO; Landscape sheets 2L, 3L, 4L; Irrigation sheet 2S RFI 45 is incorporated in these plans Robert Wagner Enviro Design Page 1 of 1

Embrey Builders, LLC 1020 N. E. Loop 410, Suite 700 Ph : (210) 824-6044 Fax: (210) 824-7656 RFI#: 199 To: Enviro Design Landscape Date: 10/19/2012 7424 Greenville Ave, Suite 200 Job: EB-02 Keller Springs Lofts Dallas, TX 75231 Ph: 214/987-3010 Fax: 214/987-3015 Phone: 877-777-5115 cc: Walter Kilroy (BGO) Subject: side walk elevation conflicts Spec Section: Drawing: 2C Schedule Impact: None Cost Impact: None Date Required: 10/26/2012 On the attached blow-up detail from sheet 2C there are several elevation problems. At the point where the City sidewalk meets the sidewalk from the B2 Part.4 unit there is a low spot elevation that doesn't seem to work. Also the steps from the patio for that same unit do not seem to work. Please review the attachment with comments and provide further direction. Requested by: Bryan Pickler Embrey Partners, Ltd. I do not understand the issue. isn't there a curb cut where the sidewalk hits the entry drive? a curb opening puts the drive elevation at 37.00+ - our 37.20 sidewalk point drains at 2% back to the drive and requires three (5" +-) risers Answered date: October 19, 2012 Answered by: Enviro Design Landscape Page 1 of 1

Page 1 of 1

Page 1 of 1

EMBREY BUILDERS, LLC.

Ph: (210) 824-6044 Fax: (210) 824-7656

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209