

TOW	N OF ADDISON	
BUIL	DING REPORT	
Facility Information:	Facility Name: Theatre Centr	re
Facility Contact: Lisa Pyles	Contact Phone: 972-450-2878	3
Accessology Inspector Information:		
Inspector: Karen Jackson Email: Kjackson@accessology.com	D	Pate: April 19, 2017
Latitude: 32.961853	Longitude: -96.828709	
Address: 15650 Addison Road	City: Addison	County: Dallas
The parking evaluated on this re Additionally, there is an employ Total Parking Spaces: Employee Lot Total Accessible Parking Spaces: Number of van accessible spaces: Is the accessible parking substantially compliant?	port is shared with the Conference ee parking lot provided.	27 0 0 N/A
Total Parking Spaces: Public Parking Total Accessible Parking Spaces: Number of van accessible spaces: Is the accessible parking substantially compliant?		159 6 2 No
Violation #1: There are no accessible parking	spaces provided in the employee [parking lot.
Standard: 2010 ADAAG 502 Park	sing Spaces	

TOWN OF ADDISON - Theatre Centre Parking - Page 2

Text:

Car and van parking spaces shall comply with (502 Parking Spaces). Where parking spaces are marked with lines, width measurements of parking spaces and access aisles shall be made from the centerline of the markings.

Possible Solutions:

Add two (2) accessible parking spaces, one being van accessible with an access aisle and compliant signage.

Violation #1 Cost:

\$3,150

Priority

Level 4

Violation #2:

In the public parking lot, two of the accessible parking spaces are not a minimum of 96" wide: The third space is 92-1/2" wide and the fifth space is 93" wide.

Standard:

2010 ADAAG 502.2 Vehicle Spaces.

Text:

Car parking spaces shall be 96" wide minimum and van parking spaces shall be 132" wide minimum, shall be marked to define the width, and shall have an adjacent access aisle complying with 502.3.

Possible Solutions:

Restripe spaces to achieve a minimum of 96" wide car parking spaces while maintaining the 11' wide van accessible space.

Violation #2 Cost:

\$1,050

Priority

Level 4

Parking Violations Total

\$4,200

Medium Priority

High Priority

5-8

1-4

Low Priority

9-12

		OWN OF ADDISON BUILDING REPORT	
Facility Information:		Facility Name: Theatre Centre	·
Facility Contact:	Lisa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector	Information:		
-	Karen Jackson Kjackson@accessology.com		ate: April 19, 2017
Latitude:	32.961853	Longitude: -96.828709	
Address:	15650 Addison Road	City: Addison	County: Dallas
General Accessible Ro	ite Notes:		
	Comments for the exterior entrance are provided unde	route from the accessible parking to the er an additional report.	building
Does the path of travel	serve all exterior amenition building entrances to a	ouilding entrance compliant? es offered by the facility? all amenities served by the	Yes Yes Yes
Accessible Route Total	\$0	High Priority Medium Prior Low Priority	ity <u>5-8</u>

	WN OF ADDISON ILDING REPORT	
Facility Information:	Facility Name: Theatre Centre	
Facility Contact: Lisa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector Information:		
Inspector: Karen Jackson Email: Kjackson@accessology.com	Da	te: April 19, 2017
Latitude: 32.961853	Longitude: -96.828709	
Address: 15650 Addison Road	City: Addison	County: Dallas
General Entrance Notes: The entrance into the theater is the main entry door accessible? Is there an alternate door that is accessible? If so, does the inaccessible door have signage indicate of the nearest accessible door?		Yes Yes N/A
Entrance Total \$0	High Priority Medium Prior Low Priority	ity <u>5-8</u>

		WN OF ADDISON ILDING REPORT	
Facility Information:		Facility Name: Theatre Centre	e
Facility Contact: Lis	sa Pyles	Contact Phone: 972-450-2878	3
Accessology Inspector Inf	formation:		
Inspector: Ka Email: Kj	aren Jackson jackson@accessology.com	D	ate: April 19, 2017
Latitude: 32	961853	Longitude: -96.828709	
Address: 15	6650 Addison Road	City: Addison	County: Dallas
General Hallway Notes:			
Th	nis is a 2 level Theatre with	no access to the 2nd floor other than	stairs.
Is the hallway width at leader visual strobes provide Are there any protruding Is the signage substantial Violation #3:	iant hardware? maneuvering clearances? ast 36" clear width? ed? g objects? ly compliant?	loors throughout the facility that have	Yes No No Yes No No No No On No
Standard:	2010 ADAAG 404.2.7	7 Door and Gate Hardware.	
Text:	shall comply with (30	s, locks, and other operable parts on d 09.4 Operation) operable parts of such an and 48 inches maximum above the	h hardware shall
Possible Solutions:	Replace all existing kr	nob hardware with lever type hardware	re.
Violation #3 Cost:	\$13,781	Priority Level 5	

TOWN OF ADDISON - Theatre Centre Hallway - Page 2

Violation #4: Access into the ticket booth is only 28" wide where 32" minimum is required.

Standard: 2010 ADAAG 404.2.3 Clear Width.

Door openings shall provide a clear width of 32" minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees.

Possible Solutions: Modify door into ticket booth to provide 32" minimum clear width.

Violation #4 Cost: \$2,625 Priority Level 7

Violation #5: The concessions stand counter is at 45" above finished floor to the counter.

Standard: 2010 ADAAG 904.4.1 Parallel Approach.

Text:

A portion of the counter surface that is 36" long minimum and 36" high maximum above the finish floor shall be provided. A clear floor space complying with 305 shall be positioned for a parallel approach adjacent to the 36" minimum length of counter.

Possible Solutions: Modify counter to provide a 36" high and 36" long portion.

Violation #5 Cost: \$2,625 Priority Level 5

Violation #6: There is no accessible route to the 2nd floor of the building.

Standard: 2010 ADAAG 206.2.3 Multi-Story Buildings and Facilities.

TOWN OF ADDISON - Theatre Centre Hallway - Page 3

Text:

At least one accessible route shall connect each story and mezzanine in multi-story buildings and facilities.

Possible Solutions:

Install an elevator to provide access to the amenities on the 2nd floor.

Violation #6 Cost:

\$157,500

Priority

Level 4

Violation #7:

There are approximately 15 permanent signs throughout the building that are mounted in the incorrect location and do not have Braille or tactile characters.

Standard:

2010 ADAAG 703.1 General.

Text:

Signs shall comply with 703. Where both visual and tactile characters are required, either one sign with both visual and tactile characters, or two separate signs, one with visual, and one with tactile characters, shall be provided.

Possible Solutions:

Replace with compliant signage on the hinge side of the doors.

Violation #7 Cost:

\$3,938

Priority

Level 5

Violation #8:

The scene shop has 2 doors in a series with only 13-1/2" between doors.

Standard:

2010 ADAAG 404.2.6 Doors in Series and Gates in Series.

Text:

The distance between two hinged or pivoted doors in series and gates in series shall be 48" minimum plus the width of doors or gates swinging into the space.

TOWN OF ADDISON - Theatre Centre Hallway - Page 4	
Hallway - Page 4	
Possible Solutions: Remove one of the doors to alleviate doors in series condition.	
Violation #8 Cost: \$2,625 Priority Level 6	
Multiple doors throughout the Theatre (3 offices, board room, crew restroom, Violation #9: Theatre staff only area and the scene shop) do not have the minimum 18" maneuvering clearance on the pull side.	
Standard: 2010 ADAAG 404.2.4.1 Swinging Doors and Gates.	
Text: Swinging doors and gates shall have maneuvering clearances complying with Table 404.2.4.1.	ıg
Possible Solutions: Modify doors to provide 18" minimum clearance.	
Violation #9 Cost: \$18,375 Priority Level 7	
High Priority 1-4	
Hallway Total \$201,469 Medium Priority 5-8	}
Low Priority 9-12	_

		TOWN OF ADDISON BUILDING REPORT	
Facility Information:		Facility Name: Theatre Centre	
Facility Contact: Li	sa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector In	formation:		
Inspector: Ka Email: K	aren Jackson jackson@accessology.co		: April 19, 2017
Latitude: 32	2.961853	Longitude: -96.828709	
Address: 15	6650 Addison Road	City: Addison	County: Dallas
General Restroom Notes:			
re the cr	strooms on the 2nd floor e 2nd floor. There are res ew restroom. m substantially complia		e route to well as a
Does the room have the r Is the water closet substa	•	•	No No
Does the water closet hav	• •	or space?	No
Is the lavatory substantia	-	or space.	No
Is the urinal substantially	•		N/A
Is the mirror substantiall	y compliant?		No
Violation #10:	ne crew shower room is to	soo small and is has no compliant fixtures.	
Standard:	2010 ADAAG 213.	.2 Toilet Rooms and Bathing Rooms.	
Text:		are provided, each toilet room shall comply ms are provided, each bathing room shall co	
Possible Solutions:	Modify room to prodispensers.	ovide accessible water closet, shower stall, l	lavatory and
Violation #10 Cost:	\$10,500	Priority Level 4]

TOWN OF ADDISON - Theatre Centre Restrooms - Page 2

Violation #11:

Text:

Dressing room #5 is noted to be the accessible dressing room. There is a restroom with a shower provided that is too small and is not fully accessible.

Standard: 2010 ADAAG 222.1 General.

Where dressing rooms, fitting rooms, or locker rooms are provided, at least 5 percent, but no fewer than one, of each type of use in each cluster provided shall comply with 803.

Possible Solutions: Modify dressing room to provide fully accessible restroom/shower facilities.

Violation #11 Cost: \$6,300 Priority Level 4

Violation #12: Men's Restroom - Accessible stall is only 36.5" wide.

Standard: 2010 ADAAG 604.8.1.1 Size.

Wheelchair accessible compartments shall be 60" wide minimum measured perpendicular to the side wall, and 56" deep minimum for wall hung water closets and 59" deep minimum for floor mounted water closets measured perpendicular to the rear wall.

Possible Solutions: Modify restroom to provide an fully accessible stall.

Violation #12 Cost: \$4,200 Priority Level 4

Violation #13: Men's Room - Stall door is not self-closing.

Standard: 2010 ADAAG 604.8.1.2 Doors.

TOWN OF ADDISON - Theatre Centre Restrooms - Page 3

Priority

Level 7

Text:	The door shall be self-closing.
Possible Solutions:	Install a self-closing mechanism on the stall door.

Men's Room - Flush control is on the closed side of the stall.

\$105

Standard: 2010 ADAAG 604.6 Flush Controls.

Violation #13 Cost:

Violation #14:

Text:

Text: Flush controls shall be located on the open side of the water closet.

Possible Solutions: Replace flush valve to the open side of the water closet.

Violation #14 Cost: \$525 Priority Level 5

Violation #15: Men's Restroom - Coat hook is mounted at 66.5" above finished floor.

Standard: 2010 ADAAG 308.2.1 Unobstructed Front Reach. 2010 ADAAG 308.3.1 Unobstructed Side Reach

Where a forward or side reach is unobstructed, the high forward and side reaches shall be 48" maximum and the low forward and side reach shall be 15" minimum above the finish floor or ground.

Possible Solutions: Install a coat hook that is no higher than 48" above finished floor.

	TOWN OF ADDISON - Theatre Centre Restrooms - Page 4	
Violation #15 Cost:	\$105	Priority Level 7
		High Priority 1-4
Restrooms Total	\$21,735	Medium Priority 5-8
		Low Priority 9-12

	Te	OWN OF ADDISON	
	В	UILDING REPORT	
Facility Information:		Facility Name: Theatre Centre	;
Facility Contact: I	Lisa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector In	nformation:		
Inspector: F	Karen Jackson	Da	ate: April 19, 2017
Email: F	Kjackson@accessology.con	n	
Latitude: 3	32.961853	Longitude: -96.828709	
Address: 1	5650 Addison Road	City: Addison	County: Dallas
General Break Room No	otes:		
7	There is one break room ser	ving this facility.	
_			
Does the facility have a	break room?		Yes
Is there a stove or cookt	op?		Yes
Is there a sink?			Yes
Is the sink substantially	compliant?		Yes
Are the counters at 34"	aff?		Yes
_			
Violation #16:	The microwave provided is	mounted above the stove and out of rea	ach.
Standard:	2010 ADAAG 308.3	3.2 Obstructed High Reach.	
	Where a clear floor s	space allows a parallel approach to an e	lement and the
	Where a crear moor s		
Text:	high side reach is ov	er an obstruction, the height of the obst	
Text:	high side reach is ov	er an obstruction, the height of the obst depth of the obstruction shall be 24" ma	
Text:	high side reach is ov		

	TOWN OF ADDISON - Theatre Centre Break Rooms - Page 2	
Violation #16 Cost:	\$525 Priority Level 12	
	High Priority 1-4	
Break Rooms Total	\$525 Medium Priority 5-8	
	Low Priority 9-12	

		N OF ADDISON DING REPORT	
Facility Information:		Facility Name: Theatre Centre	
Facility Contact:	Lisa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector I	nformation:		
=	Karen Jackson Kjackson@accessology.com	Da	te: April 19, 2017
Latitude:	32.961853	Longitude: -96.828709	
Address:	15650 Addison Road	City: Addison	County: Dallas
General Misc Notes:	The facility includes interior drin	king fountains and transaction cou	inters.
Are there exterior drinl Are there any other mis	king fountains? scellaneous items not previously	y covered?	No N/A
Violation #17•		n the employee area is for standing quires grasping and twisting to ope	•
Standard:	2010 ADAAG 211.2 Min	imum Number.	
Text:		ng fountains shall be provided. On h 602.1 through 602.6 and one dri	_
Possible Solutions:	Install new Hi/Low drinki	ng fountain.	
Violation #17 Cost:	\$5,250	Priority Level 5	
Violation #IX.	There is only one drinking fountarequired.	in provided on the second floor, to	wo are
Standard:	2010 ADAAG 211.2 Min	imum Number.	

	TOWN OF ADDISON - Theatre Centre Miscellaneous - Page 2
Text:	No fewer than two drinking fountains shall be provided. One drinking fountain shall comply with 602.1 through 602.6 and one drinking fountain shall comply with 602.7.
Possible Solutions:	Install new Hi/Low drinking fountain.
Violation #18 Cost:	\$5,250 Priority Level 5
	High Priority 1-4
Miscellaneous Total	\$10,500 Medium Priority 5-8
	Low Priority 9-12

Summary Sheet for Theatre Centre

Theatre Centre

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add two (2) accessible parking spaces, one being van accessible with an access aisle and compliant signage.	Level 4	\$3,150.00
2	Restripe spaces to achieve a minimum of 96" wide car parking spaces while maintaining the 11' wide van accessible space.	Level 4	\$1,050.00
3	Replace all existing knob hardware with lever type hardware.	Level 5	\$13,781.00
4	Modify door into ticket booth to provide 32" minimum clear width.	Level 7	\$2,625.00
5	Modify counter to provide a 36" high and 36" long portion.	Level 5	\$2,625.00
6	Install an elevator to provide access to the amenities on the 2nd floor.	Level 4	\$157,500.00
7	Replace with compliant signage on the hinge side of the doors.	Level 5	\$3,938.00
8	Remove one of the doors to alleviate doors in series condition.	Level 6	\$2,625.00
9	Modify doors to provide 18" minimum clearance.	Level 7	\$18,375.00
10	Modify room to provide accessible water closet, shower stall, lavatory and dispensers.	Level 4	\$10,500.00
11	Modify dressing room to provide fully accessible restroom/shower facilities.	Level 4	\$6,300.00
12	Modify restroom to provide an fully accessible stall.	Level 4	\$4,200.00
13	Install a self-closing mechanism on the stall door.	Level 7	\$105.00
14	Replace flush valve to the open side of the water closet.	Level 5	\$525.00
15	Install a coat hook that is no higher than 48" above finished floor.	Level 7	\$105.00
16	Provide a microwave within the required reach range.	Level 12	\$525.00
17	Install new Hi/Low drinking fountain.	Level 5	\$5,250.00
18	Install new Hi/Low drinking fountain.	Level 5	\$5,250.00

Grand Total \$238,429.00





Violation 1 - There are no accessible parking spaces provided in the employee parking lot.




Violation 2 - Two of the accessible parking spaces are not a minimum of 96" wide: The third space is 92-1/2" wide and the fifth space is 93" wide.





Violation 3 - There are approximately 35 doors throughout the facility that have door knob style hardware requiring grasping and twisting to operate.




Violation 4 - Access into the ticket booth is only 28" wide.





Violation 5 - The concessions stand counter is at 45" above finished floor to the counter.





Violation 6 - There is no accessible route to the 2nd floor of the building.







Violation 7 - There are approximately 15 permanent signs throughout the building that are not compliant.



Violation 8 - The scene shop has 2 doors in a series with only 13-1/2" between doors.
















Violation 9 - Multiple doors throughout the theater (3 offices, board room, crew restroom, theater staff only area and the scene shop) do not have the minimum 18" maneuvering clearance on the pull side.















 $\begin{tabular}{ll} \textbf{Violation 10 -} The crew shower room is too small and is not fully compliant. \end{tabular}$







Violation 11 - Dressing room #5 is noted to be the accessible dressing room. There is a restroom with a shower provided that is too small and is not fully accessible.








Violation 12 - Men's Restroom - Accessible stall is only 36.5" wide.





Violation 13 - Men's Room - Stall door is not self-closing.



Violation 14 - Men's Room - Flush control is on the closed side of the stall.





Violation 15 - Men's Restroom - Coat hook is mounted at 66.5" above finished floor.




Violation 16 - The microwave provided is mounted above the stove and out of reach.





Violation 17 - The drinking fountain provided in the employee is for standing persons only and has no knee clearance and requires grasping and twisting to operate.



Violation 18 - There is only one drinking fountain provided on the second floor, two are required.