Alliance Geotechnical Group, Inc.

| Depth to water at completion of boring: Dry Depth to water when checked: Depth to caving when checked: | | | | | was: | | | | | | | | |
|--|--|---|---|---------|---------|---------|----------|-----------|-------------------|--------------|----------|--|--|
| LEVATION/ DEPTH (feet) | SOIL SYMBOLS SAMPLER SYMBOLS & FIELD TEST DATA | DESCRIPTION | MC % | LL % | PL % | PI % | -40 % | DD pcf | P PEN Isf | UNCON ksf | St | | |
| ۲٥ | | 9" ASPHALT over 8" very soft CLAY (FILL) w/ limestone | | - | _ | _ | | | | | + | | |
| ŀ | | fragments Dark brown and brown <u>CLAY</u> w/ tan weathered | | 51 | 18 | 33 | 61 | | 3.6 | | \vdash | | |
| | 44 | Limestone layers (FILL) | 16 | | _ | L | | | 3.4 | | - | | |
| -5 | | Dark brown CLAY | 31 | | | - | | | 3.6 3.2 1.7 | | | | |
| and a second | | Tan <u>severely weathered LIMESTONE</u> , highly fractured, w/ clay layers | | | | | | | 1.8 | | | | |
| and an area and a second | 50/4.5 | Moderately hard to hard tan <u>weathered LIMESTONE</u> , fractured, w/ clay seams | | | | | | | 4.577 | | | | |
| -20 | | | And the second control of the second | | | | | | | | | | |
| | | | | | | | | | | | | | |
| -30 | | | | | | | | | | | | | |
| | | | | | | | | | | | - | | |
| - 35 | | | | | - | | | | | | | | |

GARVER

REGISTRATION NO. F-5713

DATE DESCRIPTION BY

ADDISON

TOWN OF ADDISON
ADDISON, TX
ADDISON ROAD PAVEMENT
REHABILITATION FROM ARA

BORING LOCATIONS AND LOGS

JOB NO.: 14087020 DATE: MAY, 2015 DESIGNED BY: QGS DRAWN BY: TWM

> BAR IS ONE INCH ON ORIGINAL DRAWING

IF NOT ONE INCH O THIS SHEET, ADJUS

DRAWING NUMBER
BL-07

SHEET 40

SPACE:Garver_2012 DC02\()projects\(\)\(\)2014\(\)14087029 - Addison Rd Pavmt Rehab\(\)Drawings\(\)Alternative 3\(\)