Embrey Builders, LLC 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Erik Earnshaw
Beeler Guest Owens Architects 4245 N. Central Expressway

RFI#: 143 Date: 6/7/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

Suite 300 Dallas, TX 75205 Ph: 214/520-8878 Fax: 214/520-8879

CC: Trent Perkins (Parkin Perkins Olsen)

Subject: Window in B2 Part 1 and B2 Part 2

Drawing: A2.7 & A2.7A Cost Impact: None

Spec Section: Schedule Impact: None

Date Required: 6/15/2012 Based on the wall dimensions of the B2 unit on A2.7, the window in the LR of the B2 Part 1 and Part 2 (A2.7A) will not fit in the dimensions provided. Please check the dimensions and let me know. If the wall has to jog over, please make the jog two feet from the exterior wall.

Requested by: David Miller Embrey Builders LLC

Response: Several B2 units had this problem. See attached versions of sheets 2.7A and 2.7B.

Truss manufacturer needs to be updated of these changes because structural walls moved slightly.

Date

Ryan Faulds BGO architects July 26, 2012

Answered by

Company

Page 1 of 1