

EMBREY BUILDERS, LLC.
1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Jordan & Skala Engineers, Inc.
14240 Midway Road, Suite 350
Dallas, TX 75244
Ph: 469/385-1616 Fax: 469/385-1615

RFI #: 77
Date: 3/15/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Erik Earnshaw (BOG)

Subject: Conflicts with meter center locations and numbers

Drawing: Oncor final plan, E-10.1, 3.1C, e-3.1C Spec Section:
Cost Impact: None Schedule Impact: None

Request: Date Required: 3/22/2012

Some of the meter centers have changed location and numbers. 3.1C in Architectural and E-3.1C have different meter center numbers than the final E-10.1 and encore Final drawing. Also, E-10.1 and Oncor show two meter centers inside the garage. This must be a mistake. The meter centers should be mounted to the exterior of the building as shown on 3.1C and E-3.1C. I think we may want to have the meter center numbers match the Oncor plans and change from 3.1C and E-3.1C. These conflicts are very confusing and need to be corrected so we get them in the right place. Please see attachments and advise.

Requested by: Bryan Pickler
Embrey Partners, Ltd.

Response:

The meter centers were updated as part of rfi 96 on March 30th. The meter center names shall match those shown in the rfi 96 response. See attached for rfi response and updated drawings.

Heath Parnell

Answered by: Jordan & Skala 4-10-12
Company: Date

Page 1 of 1

EMBREY BUILDERS, LLC.
1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Heath Parnell
Jordan & Skala Engineers, Inc.
14240 Midway Road, Suite 350
Dallas, TX 75244
Ph: 469/385-1616 Fax: 469/385-1615

RFI #: 96
Date: 3/28/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: Meter Center Locations -

Drawing: E3.1A, E3.1C, E10.1 and Oncor Spec Section:
Construction Print Schedule Impact: None
Cost Impact: None

Request: Date Required: 4/4/2012

Please see the attached Oncor Construction Print. The following Meter Center locations do not match up with Oncor's layout. E3.1A - MC1B and MC2 are reversed from Oncor plan. These meter centers are also in the wrong location on E10.1. E3.1C - MC3, MC11A, MC11B and MC12 are different from Oncor plan. MC9 is OK. E10.1 also needs to match up with the Oncor plan. Please revise plans to match the Oncor layout.

Requested by: David Miller
Embrey Builders LLC

Response:

Please see attached drawings for revisions in coordination with Oncor drawings.

Mike Jennings

Answered by: Jordan & Skala Engineers 3/30/2012
Company: Date

Page 1 of 1

