1020 N. E San Anto	ey Builders, LLC E. Loop 410, Suite 700 nio, TX 78209) 824-6044 Fax: (210) 824-7656
То:	Trent Perkins Parkin Perkins Olsen 9330 LBJ Freeway, Suite 10 Dallas, TX 75243 Ph: (214)221-2220 Fax: (21
CC:	Ryan Faulds (B.G.O. Archite

RFI

y, Suite 1055 0 Fax: (214)221-2252

Date: 8/6/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

.G.O. Architects, Inc.)

Subject: A2 unit beams

Drawing: 9/S2.01, 10/S2.01, 11/S2.01, 12/S2.01 Cost Impact: None

Spec Section:

Schedule Impact: None

Request:

A2 BEAMS
The A2 units have a 2x12 FB that intersects another 2x12 FB at a 45degree angle. There is no hanger noted at these locations.
Does this beam to beam connection need a hanger? Please refer to page S2.01 details #9 #10 #11 and #12. If a hanger is needed can we use a SUR410 / SUL410 or a HSUR410 / HSUL410? I have spoken to the truss co and they have said they cannot tell us if a Date Required: 8/7/2012 hanger is needed or what size it should be.

Requested by: Bryan Pickler Embrey Partners, Ltd.

HSUR410/HSUL410 are acceptable.

R. Trent Perkins, P.E. Parkin-Perkins-Olsen Consulting Engineering, Inc.

August 10, 2012

Answered by

Company

Page 1 of 1

Date Required: 7/5/2012

Embrey Builders, LLC 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Trent Perkins Parkin Perkins Olsen 9330 LBJ Freeway, Suite 1055 Dallas, TX 75243 Ph: (214)221-2220 Fax: (214)221-2252

RFI#: 166 Date: 7/5/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

cc: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: Header Wood Species

Drawing: S2.01 Cost Impact: None

Spec Section: Schedule Impact: None

Can we use DFL in lieu of SYP for 2x12 headers?

Embrey Builders LLC

Requested by: David Miller

number 1 douglas fir-larch is an acceptable substitute for the number 2 grade southern pine at the 2x12 headers

Answered by: Trent Perkins Parkin Perkins Olsen Answered date: July 05, 2012

Page 1 of 1