EMBREY BUILDERS, LLC. 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Trent Perkins
Parkin Perkins Olsen
9330 LBJ Freeway, Suite 1055
Dallas, TX 75243
Ph: (214)221-2220 Fax: (214)221-2252

RFI #: 99

Date: 4/3/2012

Job: EB-02 Keller Springs Lofts

Phone: 877-777-5115

cc: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: B1 HC Unit Differences - Structural vs Architectural

Drawing: S2.05 & A2.6HC Cost Impact: None

Spec Section:
Schedule Impact: None

Request:

1/S2.05 shows different wall locations than the unit shown on A2.6HC. Please confirm which is correct and make revisions.

Requested by: David Miller
Embrey Builders LLC

Response:

The Architecture is correct. Please see the attached sheet S2.05 that has been revised accordingly.

R. Trent Perkins, P.E.
Parkin-Perkins-Olsen Consulting Engineering, Inc.

Answered by
Company

Date

Page 1 of 1

Embrey Builders, LLC 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Trent Perkins
Parkin Perkins Olsen
9330 LBJ Freeway, Suite 1055
Dallas, TX 75243
Ph: (214)221-2220 Fax: (214)221-2252

RFI #: 98

Date: 3/29/2012

Job: EB-02 Keller Springs Lofts

Phone: 877-777-5115

CC: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: B1 HC Floorplan

Drawing: S2.5 & A2.6HC Cost Impact: None

Spec Section:
Schedule Impact: None

Request:

The floorplan shown for the B1HC unit on S2.5 is different from the floorplan shown on A2.6HC. Please let us know which is correct.

Requested by: David Miller
Embrey Builders LLC

Response:

Architectural Drawings take precedent. Please verify with BGO that A2.6HC is correct.

R. Trent Perkins, P.E.
Parkin-Perkins-Olsen Consulting Engineering, Inc.

Answered by
Company

Date

Page 1 of 1

	•							
	•							
·								
							and the second s	
						The state of the s		
							Control of the second of the s	