EMBREY BUILDERS, LLC.

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI RFI #: 27 To: Trent Perkins Date: 1/5/2012 Parkin Perkins Olsen Job: EB-02 Keller Springs Lofts 9330 LBJ Freeway, Suite 1055 Dallas, TX 75243 Phone: 877-777-5115 Ph: (214)221-2220 Fax: (214)221-2252 Subject: Top of wall step up Spec Section: Drawing: SG2.01 Schedule Impact: None Cost Impact: None Date Required: 1/12/2012 On sheet SG2.01 at the intersection of grid 8 + B shows to step Top Of Wall up 3'-0" - Ref 12/SG3.01, how long is step up, why is there a step up, and what is the step up for? Please advise Requested by: Bryan Pickler Embrey Partners, Ltd. This note is left over from a previous revision and should be deleted. If you have questions or require additional information regarding this matter, please do not hesitate to contact us.

Page 1 of 1

Brande Parkey Answered by Parkin-Perkins-Olsen

Company