A C C E S S O L O G Y	
	ΔΓ

Г

ADDISON AIRPORT					
BUILDING REPORT					
Facility Information:Facility Name: 4660 Jimmy Doolittle Drive					
Facility Contact:	Lisa Pyles	Contact Phone: 972-450-2878	}		
Accessology Inspector	Information:				
Inspector:	Karen Jackson	D	pate: April 17, 2017		
Email:	Kjackson@accessology.com				
Latitude:	32.967365	Longitude: -96.832866			
Address:	4660 Jimmy Doolittle Drive	City: Addison	County: Dallas		
General Parking Notes	:				
Total Parking Spaces: Total Accessible Parkir Number of van accessil Is the accessible parkin	ng Spaces: ble spaces: ng substantially compliant?	e is provided to indicate accessible	e parking exists. 7 1 1 Yes		
Violation #1:	There is an accessible parking sp	pace, but no signage is provided.			
Standard:	2010 ADAAG 502.6 Ide	entification.			
Text:	accessible." Signs shall	cking spaces shall contain the designed be 60 inches minimum above the following the bottom of the sign.	Ŧ		
Possible Solutions:	Add a Van Accessible pa	arking sign.			

	ADDISON AIH	ADDISON AIRPORT - 4660 Jimmy Doolittle Drive Parking - Page 2	
Violation #1 Cost:	\$525	Priority Level 7	
		High Priority 1-4	
Parking Violations Total	\$525	Medium Priority 5-8	
		Low Priority 9-12	

ADDISON AIRPORT BUILDING REPORT					
Facility Information:	Facility Name: 4660 Jimmy Doolittle Drive				
Facility Contact: Lisa Pyles	Contact Phone: 972-450-2878				
Accessology Inspector Information:					
Inspector: Karen Jackson Email: Kjackson@accessology.com	Date: April 17, 2017				
Latitude: 32.967365	Longitude: -96.832866				
Address: 4660 Jimmy Doolittle Drive	City: Addison County: Dallas				
General Accessible Route Notes: The accessible route to the building entrance is substantially compliant. Is the path of travel from accessible parking to building entrance compliant? Yes Does the path of travel serve all exterior amenities offered by the facility? N/A Is the path of travel from building entrances to all amenities served by the N/A entrance substantially compliant? N/A					
Accessible Route Total \$0	High Priority1-4Medium Priority5-8Low Priority9-12				

ADDISON AIRPORT BUILDING REPORT				
Facility Information:	Facility Name: 4660 Jimmy Do	polittle Drive		
Facility Contact: Lisa Pyles	Contact Phone: 972-450-2878			
Accessology Inspector Information:				
Inspector: Karen Jackson Email: Kjackson@accessology.com	Dat	te: April 17, 2017		
Latitude: 32.967365	Longitude: -96.832866			
Address: 4660 Jimmy Doolittle Drive	City: Addison	County: Dallas		
General Entrance Notes: The entrance door into the facil Is the main entry door accessible? Is there an alternate door that is accessible? If so, does the inaccessible door have signage indicati of the nearest accessible door?	· · · ·	Yes N/A N/A		
Entrance Total \$0	High Priority Medium Priori Low Priority			

ADDISON AIRPORT							
BUILDING REPORT							
Facility Information:		Facility Name: 4660 Jimm	y Doolittle Drive				
Facility Contact: Lisa	Pyles	Contact Phone: 972-450-28	78				
Accessology Inspector Infor	mation:						
Inspector: Kares	Inspector: Karen Jackson Date: April 17, 2017						
Email: Kjacl	cson@accessology.com						
Latitude: 32.96	Latitude: 32.967365 Longitude: -96.832866						
Address: 4660	Jimmy Doolittle Drive	City: Addison	County: Dallas				
General Hallway Notes: This is a small facility with a couple of an open office area, one office and a unisex restroom. Does this facility have any hallways? Yes Do the doors have compliant hardware? No Do the doors have proper maneuvering clearances? Yes Is the hallway width at least 36" clear width? Yes Are visual strobes provided? No Are there any protruding objects? No Is the signage substantially compliant? No We be the use of the door into the Executive Offices has knob style door hardware requiring It is the signage substantially compliant?							
Violation #2: grasp	ing and twisting to operate. 2010 ADAAG 404.2.7 Do	or and Gate Hardware.					
Text:	Handles, pulls, latches, loc shall comply with 309.4.	ks, and other operable parts o	n doors and gates				
Possible Solutions:	Replace all knob hardware grasping or twisting to ope	with lever hardware that does rate.	sn't require tight				

	ADDISON AIRPORT - 4660 Jimmy Doolittle Drive Hallway - Page 2		
Violation #2 Cost:	\$525	Priority Level 5	
		High Priority 1-4	
Hallway Total	\$525	Medium Priority 5-8	
		Low Priority 9-12	

ADDISON AIRPORT BUILDING REPORT						
Facility Information:		Facility Name: 4660 Jimmy De	oolittle Drive			
Facility Contact:	Lisa Pyles	Contact Phone: 972-450-2878				
Accessology Inspector I	nformation:					
-	Inspector: Karen JacksonDate: April 17, 2017Email: Kjackson@accessology.com					
Latitude:	32.967365	Longitude: -96.832866				
Address:	4660 Jimmy Doolittle Drive	City: Addison	County: Dallas			
General Restroom Note	s:					
	There is one unisex restroom prov	ided in this facility.				
Is the water closet subst Does the water closet ha Is the lavatory substant Is the urinal substantial Is the mirror substantia Violation #3:	ave the required clear floor spac ially compliant? lly compliant?	unted on the face of the door and	°			
Standard:	2010 ADAAG 216.2 Desig	gnations.				
Text: Interior and exterior signs identifying permanent rooms and spaces shall comply with 703.1, 703.2, and 703.5. Where pictograms are provided the pictograms shall comply with 703.6 and shall have text descriptors complying with 703.2 and 703.5.						
Possible Solutions:	Possible Solutions: Provide new compliant signage amd install it on the latch side of the door.					
Violation #3 Cost:	\$525	Priority Level 5				

	ADDISON AIRPORT - 4660 Jimmy Doolittle Drive			
	Restrooms - Page 2			
Violotion #/	The restroom is not large enough to accommodate accessible fixtures and a wheelchair turning space.			
Standard:	2010 ADAAG 213.2 Toilet Rooms and Bathing Rooms.			
Text:	Where toilet rooms are provided, each toilet room shall comply with 603. Where bathing rooms are provided, each bathing room shall comply with 603.			
Possible Solutions:	Enlarge restroom to accommodate accessible water closet, lavatory and wheelchair turning space.			
Violation #4 Cost:	\$8,400 Priority Level 3			
Violation #5:	The coat hook is mounted at 66" where 48" is the maximum allowed.			
Standard:	2010 ADAAG 308.3.1 Unobstructed.			
Text:	Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48" max. and the low side reach shall be 15" min. above the finish floor.			
Possible Solutions:	Lower coat hook so its at 48" above finished floor.			
Violation #5 Cost:	\$105 Priority Level 12			
	High Priority 1-4			
Restrooms Total	\$9,030 Medium Priority 5-8			
	Low Priority 9-12			

Summary Sheet for 4660 Jimmy Doolittle Drive


4660 Jimmy Doolittle Drive

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add a Van Accessible parking sign.	Level 7	\$525.00
2	Replace all knob hardware with lever hardware that doesn't require tight grasping or twisting to operate.	Level 5	\$525.00
3	Provide new compliant signage amd install it on the latch side of the door.	Level 5	\$525.00
4	Enlarge restroom to accommodate accessible water closet, lavatory and wheelchair turning space.	Level 3	\$8,400.00
5	Lower coat hook so its at 48" above finished floor.	Level 12	\$105.00

Grand Total \$

\$10,080.00





Violation 2 - The door into the Executive Offices has knob style door hardware requiring grasping and twisting to operate.





Violation 3 - The restroom sign provided is mounted on the face of the door and the door swing outward. Additionally, the signage does not have Braille or tactile characters.



Violation 4 - The restroom is not large enough to accommodate accessible fixtures and a wheelchair turning space.



