

Replace existing storefront door with new storefront door. Field verify existing conditions to maximize width of door opening.


Repair / Refinish and Repaint existing wood gymnasium flooring.

Remove existing overhead door. Infill opening with metal stud partition. Interior grade plywood finish to the gymnasium side, "Densglass" exterior sheathing and stucco finish to match adjacent surfaces on the exterior.

DANIEL COOK ARCHITECT
1710 NORTH BELLS FORT
SUITE 200
DALLAS, TEXAS 75248
PHONE: 972-967-2883

BCA
BUILDING CODES ASSOCIATION
OF TEXAS

THE DESIGN IS CONSIDERED AS PART OF AN APPROVED COLLECTION OF WORK. ANY REVISIONS TO THE DESIGN SHALL BE THE RESPONSIBILITY OF THE ARCHITECT. THE ARCHITECT SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL, STATE OR FEDERAL AGENCIES OR AGENCIES OF THE STATE OF TEXAS. THE ARCHITECT SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL, STATE OR FEDERAL AGENCIES OR AGENCIES OF THE STATE OF TEXAS. THE ARCHITECT SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL, STATE OR FEDERAL AGENCIES OR AGENCIES OF THE STATE OF TEXAS.



TRINITY CHRISTIAN
ACADEMY
17001 ADDISON ROAD
ADDISON, TX 75001-5096

NO.	DATE	DESCRIPTION	BY	APP.	ORIGINAL ISSUE
1	05-15-05	Original Issue			
2	05-15-05	Current Issue			

Current Revision
Current Issue Date
05-15-05
Original Issue Date
05-15-05
Architect
FORREST
Draftsman
FORREST

FLOOR PLANS

PROJECT AS081
A-01
DO NOT SCALE DRAWINGS!