



NOTE:  
 LOCATION OF PAVEMENT CRACKS, PATCHES, AND HOLES SHOWN ARE APPROXIMATE ONLY. FINAL LOCATIONS AND REPAIR METHOD DETERMINATION FOR EACH PAVEMENT CRACK, PATCH, AND HOLE WILL BE AS DIRECTED BY THE OWNER'S REPRESENTATIVE.



NO.	REVISION	BY	DATE

DESIGNED BY: DRS  
 DRAWN BY: PBSJ  
 CHECKED BY: WSF  
 SCALE: 1"=100' (H)  
 DATE: AUGUST 2002  
 FILE: 949-PVMT REPAIR PLAN.DWG



**PBSJ**  
 5999 Summerside Drive, Suite 202  
 Dallas, Texas 75252 (972)380-2605

Town of Addison  
 Dallas County  
 Texas

BELT LINE ROAD  
 PAVEMENT GROOVING IMPROVEMENTS  
**"PAVEMENT REPAIR PLAN"**  
 TOWN OF ADDISON  
 AUGUST, 2002

SHEET NO. 4  
 OF 6 SHEETS  
 JOB NO. 450949