

The trap should be cleaned when the capacity has been reduced

by $\frac{1}{2}$ or the sediment has accumulated to a depth of 1',

whichever is less.

on the plans

SECTION D-D

EC693.DGN

REVISIONS

TxDOT MAY 1993

DN: HEJ CK: HEJ DW: BGD

FEDERAL AID PROJECT

CONTROL SECT JOB HIGHWAY