

**Embrey Builders, LLC**  
1020 N. E. Loop 410, Suite 700  
San Antonio, TX 78209  
Ph: (210) 824-6044 Fax: (210) 824-7656

**RFI**

**To:** Erik Earnshaw  
Beeler Guest Owens Architects  
4245 N. Central Expressway  
Suite 300  
Dallas, TX 75205  
Ph: 214/520-8878 Fax: 214/520-8879

**RFI #:** 138  
**Date:** 6/1/2012  
**Job:** EB-02 Keller Springs Lofts  
**Phone:** 877-777-5115

**CC:**

**Subject:** Window Header Height

**Drawing:** A2.0  
**Cost Impact:** None

**Spec Section:**  
**Schedule Impact:** None

**Request:** A2.0 calls out the standard header height to be 9'-0". This height will not work in situations where there is a 2x12 header. This occurs in several unit types. Please let us know if you would like to remove the top plate or drop the standard header height down a couple of inches.  
**Date Required:** 6/11/2012

**Requested by:** David Miller  
Embrey Builders LLC

**Response:** Yes.  
I agree.  
But, taking out the bottom top plate is only need when a 2x12 header is used.

Ryan Faulds  
BGO architects  
June 28, 2012

Answered by \_\_\_\_\_

Company \_\_\_\_\_

Date \_\_\_\_\_