

EMBREY BUILDERS, LLC.
1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Jordan & Skala Engineers, Inc.
14240 Midway Road, Suite 350
Dallas, TX 75244
Ph: 469/385-1616 Fax: 469/385-1615

RFI #: 32
Date: 1/12/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Erik Earnshaw (BGO)

Subject: B2 master Bathroom Toilet

Drawing: Arch 2.7 P2.6
Cost Impact: None

Spec Section:
Schedule Impact: None

Request: Heath our Plumber requested a RFI. In the master bathroom on the B2 unit the toilet is not centered on the wall is this correct?
Date Required: 1/16/2012

Requested by: Bryan Pickler
Embrey Partners, Ltd.

Response:

It is acceptable to center the water closet in bathroom #1 for the B2 units as requested.

Erik Earnshaw

Answered by: BGO
Company: BGO
Date: 01-23-2012