

Embrey Builders, LLC

1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 824-8044 Fax: (210) 824-7656

RFI

To: Trent Perkins
Parkin Perkins Olsen
9330 LBJ Freeway, Suite 1055
Dallas, TX 75243
Ph: (214)221-2220 Fax: (214)221-2252

RFI #: 98
Date: 3/29/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: B1 HC Floorplan

Drawing: S2.5 & A2.6HC
Cost Impact: None

Spec Section:
Schedule Impact: None

Request: Date Required: 4/6/2012
The floorplan shown for the B1HC unit on S2.5 is different from the floorplan shown on A2.6HC. Please let us know which is correct.

Requested by: David Miller
Embrey Builders LLC

Response:

Architectural Drawings take precedent. Please verify with BGO that A2.6HC is correct.
R. Trent Perkins, P.E. June 14, 2012
Parkin-Perkins-Olsen Consulting Engineering, Inc.

Answered by _____
Company _____ Date _____

