

Embrey Builders, LLC
1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 824-6044 Fax: (210) 824-7856

RFI

To: Ryan Faulds
B.G.O. Architects, Inc.
4245 N. Central Expressway
Dallas, TX 75205
Ph: (210) 829-1898 Fax: (210) 829-1899

RFI #: 173
Date: 7/12/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: wrong dimension on sheet 3.1F

Drawing: 3.1F Spec Section:
Cost Impact: None Schedule Impact: None

Request: Date Required: 7/19/2012
The dimension of 35'- 4 1/2" by MC18 needs to be changed to 31'-10". For proper documentation purposes, please revise and reissue a new revision of sheet 3.1F showing the proper dimension.

Requested by: Bryan Pickler
Embrey Partners, Ltd.

Response: I talked with Brian Peterson on this issue and verified this dimension update so he wasn't delayed in the field waiting on this drawing. (see updated 3.1F on next page of this PDF)

Ryan Faulds
BGO architects
July 30, 2012

Answered by _____
Company _____

Date _____