

Embrey Builders, LLC
1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 824-6044 Fax: (210) 824-7656

RFI

To: Ryan Faulds
B.G.O. Architects, Inc.
4245 N. Central Expressway
Dallas, TX 75205
Ph: (210)829-1898 Fax: (210)829-1899

RFI #: 205
Date: 11/9/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Walter Kilroy (BGO)

Subject: B windows in the upperfloors of the public areas

Drawing: 3.2B, 3.3B, 3.4B, 3.2D, 3.3D, 3.4D
Cost Impact: None

Spec Section:
Schedule Impact: None

Request: **Date Required:** 11/16/2012
There are (6) B windows in the upper floors of the public corridor shown on sheets 3.2B, 3.3B, 3.4B, 3.2D, 3.3D, & 3.4D. Since these windows are in a public area shouldn't they be fixed windows & not operable windows?
Requested by: Bryan Pickler
Embrey Partners, Ltd.

Response:
The window sizes are correct, and yes, these should be fixed, non-operable windows.

Answered by: Ryan Faulds
B.G.O. Architects, Inc.

Answered date: November 12, 2012