EMBREY BUILDERS, LLC. 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

DEI

To: Erik Earnshaw **BGO Architects** 4144 N. Central Expressway Suite 855 Dallas, TX 75205

RFI#: 42 Date: 1/26/2012 Job: EB-02 Keller Springs Lofts

Phone: 877-777-5115

Ph: (214)520-8878 cc: David Gallagher (Embrey Build (Embrey Construction LLC)

Subject: Elevation conflict B2 alt 3 unit

Drawing: 3.2D, 3.2F, and 4.1

Ryan Faulds

Company

Answered by BGO architects

Schedule Impact: None

Spec Section:

Cost Impact: None Date Required: 2/2/2012 On sheet 3.2D the B2 alt 3 unit on the 2nd, 3rd, and 4th floors are all marked with a H. Sheet 4.1 these unit's windows are drawn as (2) E marked windows, this also happens in the B2 alt F units in division F. Please give direction. Requested by: Bryan Pickler Embrey Partners, Ltd. Response to this RFI can be found on RFI- 40.

Feb 24, 2012

Date

Page 1 of 1