```
EMBREY BUILDERS, LLC.
```

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Erik Earnshaw **BGO Architects** 4144 N. Central Expressway Suite 855 Dallas, TX 75205

Ph: (214)520-8878

RFI#: 61 Date: 2/22/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115

cc: David Gallagher (Embrey Builders LLC)

Subject: Fire Extinguisher Cabinets Locations

Drawing: 3.1A, 3.2A, 3.3A, 3.4A, 3.4F

Spec Section: Schedule Impact: None Cost Impact: None

Date Required: 2/29/2012 1) There are some inconsistency's with plans for FEC locations in corridors.
3.1A shows 2 FEC
3.2A shows 1 FEC
3.3A shows 1 FEC
3.4A shows 2 FEC Do you want 2nd FEC added for 2nd & 3rd floors? 2) On sheet 3.4F - FEC mark is missing on A4 Alt G wall.
The FEC is shown on 1st, 2nd and 3rd floors, does the FEC need to be included at 4th floor?
Please verify all sections for coordination and consistency. 3) Do we need fire extinguishers in club/leasing? We have assumed 1 for club and 1 for leasing. 4) Do we need FE in parking garage and if so what type of mounting?

Requested by: Bryan Pickler Embrey Partners, Ltd.

2- Yes. I've checked all locations and the one's you mentioned are the only problem locations. I adjusted 2 other FEC locations by moving them a foot or so now all FECs line up in the same spot from floor to floor (except for the Club and Garage areas).

3- I've placed the 2 FECs you mentioned in sheet 9.1

4- Yes, we need them in the parking garage. I've updated the sheets to reflect this. Double check with your local Fire Marshall, but I'm confidant that a surface mounting will be fine.

Ryan Faulds

Answered by BGO architects

Feb 28, 2012

Company

Page 1 of 1