EMBREY BUILDERS, LLC.

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Erik Earnshaw
BGO Architects
4144 N. Central Expressway
Suite 855

RFI #: 81

Date: 3/20/2012

Job: EB-02 Keller Springs Lofts

Phone: 877-777-5115

Dallas, TX 75205 Ph: (214)520-8878

CC: David Gallagher (Embrey Build (Embrey Construction LLC)

Subject: Pitch of the roof crickets

Drawing:

Cost Impact: None

Spec Section:
Schedule Impact: None

Request:

Roof crickets

We have not been able to find the pitch of the roof top crickets. The pitch of the main roof is given as a 3/8 inch pitch. Not sure if you want the typical ½ inch per foot fall or do you want the crickets to have the same pitch (3/8) as the main roof. Please give us the pitch of the roof top crickets.

Requested by: Bryan Pickler

Embrey Partners, Ltd.

Response:

We didn't give the slopes for every little cricket because that leans more towards 'Means and Methods.' A minimum of 3/8" per foot slope is acceptable for all crickets. If you need a detail for a certain part of the roof, I'll create that for you.

Ryan Faulds

Answered by BGO architects

Company

March 22, 2012

Date

Page 1 of 1