EMBREY BUILDERS, LLC. 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

		RFI
E 2 3	Erik Earnshaw BGO Architects 4144 N. Central Expressway Suite 855 Dallas, TX 75205 Ph: (214)520-8878	RFI #: 43 Date: 1/26/2012 Job: EB-02 Keller Springs Lofts Phone: 877-777-5115
CC:	David Gallagher (Embrey Build (Embrey Co	onstruction LLC)
Subject:	Elevation conflict 4.7 #4	
Drawing Cost Im	ı: 4.7 #4 pact: None	Spec Section: Schedule Impact: None
Request: On elevations 4.7 #4 in the a4 alt G unit the elevations show a mark wand the floor plans call for a mark B. Please advise.		
Requested by: Bryan Pickler Embrey Partners, Ltd.		
Respon	The elevation for unit Active plan has been updated as see next page.	4 alt G is drawn correctly. ated.
Ryai	n Faulds	
Answe BGC	red by O architects	Feb 24, 2012
Company		Date

Page 1 of 1