EMBREY BUILDERS, LLC. 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656	
То:	Erik Earnshaw BGO Architects 4144 N. Central Expressway

Suite 855

Company

Ph: (214)520-8878

cc: David Gallagher (Embrey Build (Embrey Construction LLC)

Subject: Elevation Conflict sheet 4.6

Dallas, TX 75205

Spec Section: Drawing: 4.6 Schedule Impact: None Cost Impact: None Date Required: 2/2/2012 On elevation 4.6 #4 the A1 unit does not match floor plans. Elevations show 2 windows not a door. Please give direction. Requested by: Bryan Pickler Embrey Partners, Ltd. Response: I'm not sure what happened here, but drawing 4/ 4.6 has been updated. The floor plans are accurate. see next page for more info. Ryan Faulds Answered by BGO architects Feb 24, 2012 Date

RFI

Date: 1/26/2012

Phone: 877-777-5115

Job: EB-02 Keller Springs Lofts

Page 1 of 1