

**EMBREY BUILDERS, LLC.**

1020 N. E. Loop 410, Suite 700  
San Antonio, TX 78209  
Ph: (210) 824-6044 Fax: (210) 824-7656

**RFI**

To: Jordan & Skala Engineers, Inc.  
14240 Midway Road, Suite 350  
Dallas, TX 75244  
Ph: 469/385-1616 Fax: 469/385-1615

RFI #: 73  
Date: 3/12/2012  
Job: EB-02 Keller Springs Lofts  
Phone: 877-777-5115

CC: David Gallagher (Embrey Builders LLC)

Subject: Proper location of gas meter

Drawing: C10 P-3.1C  
Cost Impact: None

Spec Section:  
Schedule Impact: None

**Request:**  
The location for the gas meter appears to have changed from its original location reflected on C 10 on the Civil Plans. The new location appears on the Jordan Skala SK-P1 dated 01-19-2012. It is on a completely different part of the building from C 10 and slightly different than P-3.1C. Attached is SK # 1 which is where it's located on C 10. SK # 2 reflects where I feel it is intended to be located. SK-P1 is the revised sketch by Jordan Skala locating it where we believe it is supposed to go. I need confirmation that it does go the way I show it on SK #2 and as shown on SK-P1.  
Like I said, I need the surveyors to stake the proper location tomorrow.

**Requested by:** Bryan Pickler  
Embrey Partners, Ltd.

**Response:**  
The gas meter should be located in the spots shown on SK#2 and SK-P1.

Heath Parnell

Answered by: JSS  
Company: \_\_\_\_\_  
Date: 3-12-2012