EMBREY BUILDERS, LLC.

1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Trent Perkins
Parkin Perkins Olsen 9330 LBJ Freeway, Suite 1055 Dallas, TX 75243

RFI #: 83 Date: 3/21/2012 Job: EB-02 Keller Springs Lofts

Phone: 877-777-5115 Ph: (214)221-2220 Fax: (214)221-2252

CC: Erik Earnshaw (Beeler Guest Owens Architects), Ryan Faulds (B.G.O. Architects, Inc.)

Subject: Stair Tower headers

Drawing: S2.31, S2.33, 6/S2.07 Cost Impact: None

Spec Section: Schedule Impact: None

Date Required: 3/28/2012 Stair 1 on S2.31 and Stair 9 on S2.33 call for a 3 1/2 x 11 1/4 PSL beam on one end of the stairs and no beam is called out on the other end. The other stair towers at that level do not call for that size beam. They have a note that refers all stair towers to 6/S2.07, which has different sized beams at both ends. Please check all stair towers and confirm the beam sizes to be used.

Requested by: David Miller Embrey Builders LLC

Response:

Refer to 6/S2.07 for beam sizes.

R. Trent Perkins, PE Parkin-Perkins-Olsen Consulting Engineering, Inc. March 28, 2012

Answered by

Page 1 of 1