

EMBREY BUILDERS, LLC.
1000 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph: (210) 624-6044 Fax: (210) 624-7656

RFI

To: Trent Perkins
Perkin Perkins Olson
9330 BJ Freeway, Suite 1055
Dallas, TX 75243
Ph: (214)221-2220 Fax: (214)221-2252

RFI #: 28
Date: 1/5/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC:

Subject: Pit detail

Drawing: SG2.01 & 5/SG3.02
Cost Impact: None

Spec Section:
Schedule Impact: None

Request: Date Required: 1/12/2012
On sheet Sg2.01 we have a cut through 5/SG3.02 show a pit detail at ventilation shaft. What pit and Why? Please advise

Requested by: Bryan Pickler
Embrey Partners, Ltd.

Response:

Please refer to revised drawings issued on January 25, 2012. If you have questions or require additional information regarding this matter, please do not hesitate to contact us.

Answered by: Brandt Parkey
Perkin-Perkins-Olsen
Company

Date: 01/25/2012