Embrey Builders, LLC 1020 N. E. Loop 410, Suite 700 San Antonio, TX 78209 Ph: (210) 824-6044 Fax: (210) 824-7656

\_\_\_\_

To: Trent Perkins

Parkin Perkins Olsen 9330 LBJ Freeway, Suite 1055 Dallas, TX 75243 Ph: (214)221-2220 Fax: (214)221-2252 RFI #: 132

**Date:** 5/30/2012 **Job:** EB-02 Keller Springs Lofts **Phone:** 877-777-5115

cc: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: Garage Topping Slab Details

Drawing:
Cost Impact: None

Spec Section:
Schedule Impact: None

RFI

Request:

There are no details in the plans that show any details on waterproofing, expansion joints or construction joints. These details are needed to properly form and pour the topping slab in the garage. There were no details given by the pre-cast garage sub.

Requested by: David Miller Embrey Builders LLC

lesponse:

Please refer to details on sheets SG4.01, SG4.02, and SG4.03 for structural requirements. Refer to Architectural for additional requirements.

Felt paper no wider than 8" set in mastic to hold it in place and to cover all joints between the tees, and turned up the perimeter wall the thickness of the topping

Answered by: Trent Perkins

Answered date: June 04, 2012

Parkin Perkins Olsen

Page 1 of 1

.