

TOWN OF ADDISON BUILDING REPORT			
Facility Information:		Facility Name: Addison Circle P	Park
Facility Contact: Lis	a Pyles	Contact Phone: 972-450-2878	
Accessology Inspector Info	ormation:		
Inspector: Karen Jackson Email: Kjackson@accessology.com Date: May 11, 2017			e: May 11, 2017
Latitude: 32.	Latitude: 32.960824 Longitude: -96.827594		
Address: 495	50 Addison Circle	City: Addison	County: Dallas
	Spaces:	specifically serve the park. There is paround the area.	N/A N/A N/A N/A
Parking Violations Total	\$0	High Priority Medium Priority Low Priority	y

TOWN OF ADDISON BUILDING REPORT			
Facility Information:		Facility Name: Addison Circle Pa	ark
Facility Contact: L	isa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector In	nformation:		
Inspector: K Email: K	Karen Jackson Kjackson@accessology.com	Date	: May 11, 2017
Latitude: 3	2.960824	Longitude: -96.827594	
Address: 4	950 Addison Circle	City: Addison	County: Dallas
A sidewalk and path are provided throughout the park. Comments regarding the sidewalk and path serving the park are provided in an additional report. Is the path of travel from accessible parking to building entrance compliant? N/A Does the path of travel serve all exterior amenities offered by the facility? Is the path of travel from building entrances to all amenities served by the entrance substantially compliant?			
Accessible Route Total	\$0	High Priority Medium Priority Low Priority	

TOWN OF ADDISON BUILDING REPORT			
Facility Information:		Facility Name: Addison Circle F	ark
Facility Contact: I	isa Pyles	Contact Phone: 972-450-2878	
Accessology Inspector In	nformation:		
=	Karen Jackson Kjackson@accessolo		: May 11, 2017
Latitude: 3	2.960824	Longitude: -96.827594	
Address: 4	950 Addison Circle	City: Addison	County: Dallas
General Misc Notes:	here are multiple be	enches and drinking fountains provided through	out the park.
Are there exterior drink	<u> </u>		Yes
Are there any other mis	cellaneous items no	ot previously covered?	No
Violation #1.	There is not a 30" x 4 arroughout the park.	48" clear floor space provided next to drinking for	ountains
Standard:	2010 ADAAG	G 305.3 Size.	
Text:	The clear floo minimum.	or or ground space shall be 30 inches minimum b	y 48 inches
Possible Solutions:	Provide a 30"	x 48" space next to each drinking fountain.	
Violation #1 Cost:	\$3,150	Priority Level 5]
Violation #7.	The button to operate bove ground floor.	e the dog portion of the drinking fountains is too	low at 5"
Standard:	2010 ADAAG	G 308.2.1 Unobstructed Forward Reach	
Text:	inches maxim	ard reach is unobstructed, the high forward reach aum and the low forward reach shall be 15 inches sh floor or ground.	

	TOWN OF ADDISON - Addison Circle Park Miscellaneous - Page 2		
Possible Solutions:	Relcoate or add an additional operator at 15" minimum for the dog bowl portion of the fountain.		
Violation #2 Cost:	\$525 Priority Level 12		
	High Priority		
Miscellaneous Total	\$3,675 Medium Priority		
	Low Priority		

TOWN OF ADDISON BUILDING REPORT			
Facility Information:	Facility Name: Addison Circle	e Park	
Facility Contact: Lisa Pyles	Contact Phone: 972-450-2878		
Accessology Inspector Information:			
Inspector: Karen Jackson Email: Kjackson@accessology.com Date: May 11, 2017			
Latitude: 32.960824	Longitude: -96.827594		
Address: 4950 Addison Circle	City: Addison	County: Dallas	
General Amenities Notes: The park includes benche	es and drinking fountains.		
Does each amenity have an accessible route lea	ding into it?	Yes	
Is there a playground?		No	
Does it have accessible play elements?		N/A	
Are they substantially compliant?		N/A	
Are there sports fields?		No	
Do the accessible routes extend into the dugout	?	N/A	
Is seating provided?		N/A	
Is accessible seating provided?		N/A	
Is it compliant?		N/A	
Are pavilions and/or picnic tables provided?		No	
Is an accessible route provided to them?		N/A	
Are accessible picnic tables provided?		No	
Are grills provided?		N/A	
Are they accessible?		N/A	
Violation #3: The benches throughout	the park do not provide an area for compar	nion seating.	
Standard: 2010 ADAAG 30	5.3 Size.		
Text: The clear floor or minimum.	ground space shall be 30 inches minimum	1 by 48 inches	

	TOWN OF ADDISON - Addison Circle Park Park Amenities - Page 2		
Possible Solutions:	Provide wheelchair space areas for companion seating.		
Violation #3 Cost:	\$1,050 Priority Level 5		
	High Priority		
Park Amenities Total	\$1,050 Medium Priority		
	Low Priority		

Summary Sheet for Addison Circle Park

Addison Circle Park

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Provide a 30" x 48" space next to each drinking fountain.	Level 5	\$3,150.00
12.	Relcoate or add an additional operator at 15" minimum for the dog bowl portion of the fountain.	Level 12	\$525.00
3	Provide wheelchair space areas for companion seating.	Level 5	\$1,050.00

Grand Total \$4,725.00







Violation 1 - There is not a 30" x 48" clear floor space provided next to drinking fountains throughout the park.





Violation 2 - The button to operate the dog portion of the drinking fountains is too low at 5" above ground floor.







Violation 3: - The benches throughout the park do not provide an area for companion seating.