Pre-Construction Agenda for Methodist Pavilion One June 19, 2012 Page 2 of 4

1. It is the contractor's responsibilities to minimize sediment travel onto adjacent property or streets. Erosion control must be in place as shown on the plans or as directed by the inspector. The erosion control is to be maintained until seeding has re-established vegetation. The Best Management Practices (BMP) Manual for Residential and Commercial Land Uses shall govern all erosion control measures. The construction entrance is to be used at all times. Mud in the public rights-ofway is strictly prohibited.

V. COMMUNICATION

1. The following individuals may be reached at:

Contact Name David Wilde Town Inspector	Representing Town of Addison	Phone Numbers 972-450-2847 Office 214-215-6528 Mobile
Jose T. Flores Town Inspector	Town of Addison	214-215-8569 Mobile
Lynn Chandler Building Official	Town of Addison	972-450-2889 Office
Michel Mitchell Fire Inspector	Town of Addison	972-450-7220 Office
DAVID KOCHALKA Engineer or Record	KIMLEY-HOEN	972-\$355-35% Office
		214-402-5057 Mobile
Earthwork Engineer	GILL EXCAVATING	214-134-1388 Office
		214-502-7463 Mobile
BRYAN YOLE Utility Contractor	MANERICK UTILITY	<u> ८।७ - ७८५ - ०८५८</u> Office
		817-800-4145 Mobile
		Office
Paving Contractor		Mobile
Apple HILHOUSE	ALPHA TESTING	972-620-8911 Office
Testing Laboratory		214-492-375) Mobile

VI. TESTING