

Embrey Builders, LLC
1020 N. E. Loop 410, Suite 700
San Antonio, TX 78209
Ph : (210) 824-6044 Fax: (210) 824-7656

RFI

To: Heath Parnell
Jordan & Skala Engineers, Inc.
14240 Midway Road, Suite 350
Dallas, TX 75244
Ph: 469/385-1616 Fax: 469/385-1615

RFI #: 116
Date: 5/14/2012
Job: EB-02 Keller Springs Lofts
Phone: 877-777-5115

CC: Erik Earnshaw (Beeler Guest Owens Architects)

Subject: Mechanical Plans Do Not Match Architectural Plans

Drawing: M2.11 & A2.6HC
Cost Impact: None

Spec Section:
Schedule Impact: None

Date Required: 5/22/2012
Request:
The B1-HC unit on sheet M2.11 has not been revised and doesn't match the floorplan of the B1-HC unit on A2.6HC. Please revise and reply.
Requested by: David Miller
Embrey Builders LLC

Response:
See attached for updated plan
Answered by: Heath Parnell
Jordan & Skala Engineers, Inc.
Answered date: August 23, 2012