



**TOWN OF ADDISON
Spruill Park**

Facility Information: **Facility Name:** Spruill Park
Facility Contact: Lisa Pyles **Contact Phone:** 972-450-2878

Accessology Inspector Information:
Inspector: Karen Jackson **Date:** April 4, 2017
Email: kjackson@accessology.com

Latitude: 32.963876 **Longitude:** -96.827757
Address: 4936 Marcus Avenue **City:** Addison **County:** Dallas

General Parking Notes:

Spruill Park is a 1.5 acre park located in the middle of the Fairfield Development. Parallel parking is provided on Marcus Avenue and Artist Way.

Total Parking Spaces:	18
Total Accessible Parking Spaces:	0
Number of van accessible spaces:	0
Is the accessible parking substantially compliant?	No

Violation #1: There are no marked accessible parking spaces or access aisles serving the park.

Standard: 2010 ADAAG 502 Parking Spaces

Text: Car and van parking spaces shall comply with (502 Parking Spaces). Where parking spaces are marked with lines, width measurements of parking spaces and access aisles shall be made from the centerline of the markings.

TOWN OF ADDISON - Spruill Park
Parking - Page 2

Possible Solutions:

Add one van accessible parking space with an access aisle and compliant signage. Ensure it is located where an accessible route is provided to the park.

Violation #1 Cost:

\$3,150

Priority

Level 3

Parking Violations Total

\$3,150

High Priority

1-4

Medium Priority

5-8

Low Priority

9-12

TOWN OF ADDISON

Spruill Park

Facility Information:

Facility Name: Spruill Park

Facility Contact: Lisa Pyles

Contact Phone: 972-450-2878

Accessology Inspector Information:

Inspector: Karen Jackson

Date: April 4, 2017

Email: kjackson@accessology.com

Latitude: 32.963876

Longitude: -96.827757

Address: 4936 Marcus Avenue

City: Addison

County: Dallas

General Accessible Route Notes:

A sidewalk and path are provided throughout the park. Comments regarding the sidewalk and path serving the park are provided in an additional report.

Is the path of travel from accessible parking to building entrance compliant?

N/A

Does the path of travel serve all exterior amenities offered by the facility?

N/A

Is the path of travel from building entrances to all amenities served by the entrance substantially compliant?

N/A

Accessible Route Total

\$0

High Priority

1-4

Medium Priority

5-8

Low Priority

9-12

TOWN OF ADDISON

Spruill Park

Facility Information:

Facility Name: Spruill Park

Facility Contact: Lisa Pyles

Contact Phone: 972-450-2878

Accessology Inspector Information:

Inspector: Karen Jackson

Date: April 4, 2017

Email: kjackson@accessology.com

Latitude: 32.963876

Longitude: -96.827757

Address: 4936 Marcus Avenue

City: Addison

County: Dallas

General Amenities Notes:

The park amenities include a pavilion with seating area, a bench seating area, a dual drinking fountain, trash cans and pet waste bags.

Does each amenity have an accessible route leading into it?

Yes

Is there a playground?

No

Does it have accessible play elements?

N/A

Are they substantially compliant?

N/A

Are there sports fields?

No

Do the accessible routes extend into the dugout?

N/A

Is seating provided?

N/A

Is accessible seating provided?

N/A

Is it compliant?

N/A

Are pavilions and/or picnic tables provided?

Yes

Is an accessible route provided to them?

Yes

Are accessible picnic tables provided?

N/A

Are grills provided?

No

Are they accessible?

N/A

Violation #2:

The operating mechanism for the dog bowl fountain is mounted too low at 4" high.

Standard:

2010 ADAAG 308.2.1 Reach Ranges Forward Reach Unobstructed.

TOWN OF ADDISON - Spruill Park
Park Amenities - Page 2

Text:

Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.

Possible Solutions:

Relocate or add an additional operator for the dog bowl at a minimum of 15" high.

Violation #2 Cost:

\$525

Priority

Level 7

Park Amenities Total

\$525

High Priority

1-4

Medium Priority

5-8

Low Priority

9-12

Summary Sheet for Spruill Park

Spruill Park

#	VIOLATION SUMMARY	PRIORITY LEVEL	COST
1	Add one van accessible parking space with an access aisle and compliant signage. Ensure it is located where an accessible route is provided to the park.	Level 3	\$3,150.00
2	Relocate or add an additional operator for the dog bowl at a minimum of 15" high.	Level 7	\$525.00

Grand Total	\$3,675.00
-------------	------------



Violation 1 - There are no marked accessible parking spaces or access aisles serving the park.





Violation 2 - The operating mechanism for the dog bowl provided on the drinking fountain is mounted too low at 4" above finished floor.