epth to	water at completio water when check caving when check			wa							String N
VATION/ DEPTH (feet)	SOIL SYMBOLS SAMPLER SYMBOLS & FIELD TEST DATA	DESCRIPTION	MC %	LL %	PL %	PI %	-40 %	DD pcf	P PEN tsf	UNCON ksf	
Lo		8" ASPHALT over 4" CLAY w/ limestone pieces (FILL)	+-	+	-	-					H
		Dark brown CLAY	34	79	30	49	99		4.5++ 2.6 3.3		r
and the same of th		Tan <u>severely weathered LIMESTONE</u> , highly fractured,	-	-	-	T			4.5+		
5	50/1.25" 50/1"	_w/ clay layers Moderately hard to hard tan <u>weathered LIMESTONE</u> , fractured, w/ clay seams	-				-				
	50/1 25"	Hard gray LIMESTONE	-	-	-	-				manife Specific April	
- 10	50/0 5"	Boring terminated at 10'				Ī					
-									81		
- 15											
-											
-20											
-											
ŀ											
-25											
-30											
- 35									l m		

Alliance Geotechnical Group, Inc.

Depth to water when checked: Depth to caving when checked:			was:									
DEPTH (feet)	SOIL SYMBOLS SAMPLER SYMBOLS & FIELD TEST DATA	DESCRIPTION	MC %	LL %	PL %	PI %	-40 %	DD pcf	P PEN	UNCON ksf	St	
[-0		7.5" ASPHALT over 5" very soft CLAY w/ limestone fragments (FILL)	36	64	23	41	94,		01			
and the second s		Dark brown <u>CLAY</u> w/ trace calcareous nodules	34						2.8 1.9			
- 5		Tan and gray <u>calcareous CLAY</u> -numerous limestone fragments below 7'							14 18 32 34			
10	50/4"	Moderately hard to hard tan weathered LIMESTONE, fractured, w/ clay seams			_		-					
10	50/1 5"	Boring terminated at 10'										
and in operation of the second												
- 15												
-20											-	
and the second s												
and the same of th												
- 25												
marilia managaman da mara ya m												
-30									-			
- 35												

GARVER

REGISTRATION NO. F-5713

TOWN OF ADDISON

ADDISON, TX

ADDISON ROAD PAVEMENT

REHABILITATION FROM ARAPAHO

ROAD TO NORTH TOWN LIMITS

BORING LOCATIONS AND LOGS

JOB NO.: 14087020 DATE: MAY, 2015 DESIGNED BY: QGS DRAWN BY: TWM

DRAWING NUMBER **BL-05**

SHEET 38