



Note: The contours which are indicated on these drawings as existing were taken from a Topographic Survey performed by George Collis Land Surveyors dated Sept. 15, 1993. Since that date both fill and erosion have taken place on the site, and have altered the existing conditions.

BH: Operating Nut of Fire Hydrant at SU Corner of Site.  
 Elev. = 609.16

**SITE PLAN - PART "BB"**  
**GRADING & DRAINAGE**

SCALE 1" = 30' 0"